



FACILITY ASSESSMENT REPORT


APPENDIX D




&



Appendix D Service Garage



Knoxville Civic Auditorium and Coliseum Assessment



NOTE:
 1. LAP 6x6 1/4 MESH ONE FULL SQUARE AT SIDES & ENDS.

LOADING AREA FLOOR PLAN
 SCALE: 1/16"=1'-0"



Knoxville Civic Auditorium and Coliseum Assessment



Service Garage

Knoxville Civic Auditorium and Coliseum Assessment





Truck turn area used for storage



Knoxville Civic Auditorium and Coliseum Assessment




crack

Auditorium Loading Dock

Knoxville Civic Auditorium and Coliseum Assessment






crack

Auditorium Loading Dock

Knoxville Civic Auditorium and Coliseum Assessment





Honey Combing

Spalling, Exposed and rusted rebar

crack


Water seepage thru crack

Mineral deposit at crack

North west access entrance

Knoxville Civic Auditorium and Coliseum Assessment





North west access entrance Ceiling






North west access entrance

Knoxville Civic Auditorium and Coliseum Assessment





Spalling, Exposed and rusted rebar

Mineral deposit at crack

Surface peeling

crack

Water seepage thru crack

North west access entrance

Knoxville Civic Auditorium and Coliseum Assessment





Crack

Mineral deposit at crack

Surface peeling

Spalling

Mineral deposit at crack

crack

North west access entrance

Knoxville Civic Auditorium and Coliseum Assessment





Seepage

Exposed and rusted rebar

North west access entrance






Spalling

North west access entrance





Seepage

Cracks

North west access entrance
Knoxville Civic Auditorium
and Coliseum Assessment





Seepage

Exposed and rusted rebar

North west access entrance






Seepage

Exposed and rusted rebar

North west access entrance






Seepage at
crack

Exposed and rusted rebar

Fragmented and
deteriorated concrete

North west access entrance






Fragmented and
Deteriorated
concrete

seepage

North west access entrance





Seepage

Fragmented and
deteriorated concrete

North west access entrance





Spalling

Exposed and rusted rebar


North west access entrance






North west access entrance





Electrical Switch Box





Seepage

Repair joint

West Wall





West Wall





West Wall






Mineral deposit

West Wall





West Wall





Mineral deposit at crack

Mineral deposit at crack

Infiltration & Seepage

East Wall



Knoxville Civic Auditorium and Coliseum Assessment



Mineral deposit at crack

East Wall





Mineral deposit at crack

Mineral deposit at crack

East Wall

Knoxville Civic Auditorium and Coliseum Assessment





Mineral deposit at crack

East Wall






Mineral deposit at crack

East Wall

Knoxville Civic Auditorium and Coliseum Assessment





Seepage thru
Foam fastener
holes

East Wall





Seepage

East Wall






Access to Coliseum Level 2
Knoxville Civic Auditorium and Coliseum Assessment







Mineral deposit and seepage at Joint

Mineral deposit at crack

Mineral deposit at crack

Coliseum Access Ceiling

Knoxville Civic Auditorium and Coliseum Assessment





Water Seepage & Mineral deposit at Joint

Coliseum Access Ceiling

Knoxville Civic Auditorium and Coliseum Assessment







Coliseum Entrance





Seepage

Coliseum Entrance





Seepage

Exposed and rusted rebar


Coliseum Entrance Ceiling





Coliseum Entrance Ceiling






Coliseum Access Ceiling

Knoxville Civic Auditorium and Coliseum Assessment





Mineral deposit at crack

Mineral deposit at crack

Mineral deposit at crack

Mineral deposit at crack

Mineral deposit at crack

Coliseum Access Ceiling

Knoxville Civic Auditorium and Coliseum Assessment





Mineral deposit at joint

Service Garage Ceiling





Mineral deposit at joint

Service Garage Ceiling





Mineral deposit at joint

Service Garage Ceiling





Service Garage Ceiling





Mineral deposit at construction joint

Service Garage Ceiling




Mineral
deposit at
crack

Service Garage Ceiling
















Entrance Ramp






Ramp Ceiling



Knoxville Civic Auditorium and Coliseum Assessment



Joint at Ramp Ceiling

Ramp Ceiling



Knoxville Civic Auditorium and Coliseum Assessment



Ramp West Wall





Spalling

Seepage at construction joint

Ramp Ceiling





Seepage
thru crack

Ramp wall





Seepage
thru Joint

Excessive gap at
expansion joint

Ramp wall





crack

Excessive gap at
expansion joint

Ramp wall






Excessive gap at expansion joint

Ramp wall






Ramp wall

Excessive gap at
expansion joint

Seepage
thru Joint





Seepage

Ramp wall





Ramp east wall

Knoxville Civic Auditorium and Coliseum Assessment





Infiltration & Seepage

Infiltration & Seepage

Infiltration & Seepage

Crack

Infiltration & Seepage

Crack

Ramp east wall

Knoxville Civic Auditorium and Coliseum Assessment





Entrance Ramp

Knoxville Civic Auditorium and Coliseum Assessment

