



## FACILITY ASSESSMENT REPORT

### APPENDIX A




&



#### Appendix A Exterior

|                    |                   |                 |
|--------------------|-------------------|-----------------|
| <b>Appendix A1</b> | <b>North Side</b> | <b>13 Sheet</b> |
| <b>Appendix A2</b> | <b>East Side</b>  | <b>19 Sheet</b> |
| <b>Appendix A3</b> | <b>West Side</b>  | <b>27 Sheet</b> |
| <b>Appendix A4</b> | <b>South Side</b> | <b>15 Sheet</b> |




# Knoxville Civic Auditorium and Coliseum Assessment

EAST FACE



NORTH FACE

SOUTH FACE




WEST FACE



# Knoxville Civic Auditorium and Coliseum Assessment

APPENDIX A1 NORTH FACE  
Sheet 2 of 13



Knoxville Civic Auditorium and Coliseum Assessment



Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A1 NORTH FACE**  
**Sheet 4 of 13**




Knoxville Civic Auditorium and Coliseum Assessment



Water infiltration thru gap





Cracked pavement

Water infiltration thru gap













## Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A1 NORTH FACE**  
**Sheet 11 of 13**




Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A1 NORTH FACE**  
Sheet 12 of 13



Crack at knee wall






# Knoxville Civic Auditorium and Coliseum Assessment

EAST FACE



NORTH FACE

SOUTH FACE




WEST FACE




Knoxville Civic Auditorium and Coliseum Assessment





# Knoxville Civic Auditorium and Coliseum Assessment



Knoxville Civic Auditorium and Coliseum Assessment



Spalling and water penetration



## Knoxville Civic Auditorium and Coliseum Assessment



Deformed grating



Knoxville Civic Auditorium and Coliseum Assessment

APPENDIX A2 EAST FACE  
Sheet 6 of 19













Subsurface loss,  
water intrusion, sink  
hole formation





Subsurface loss,  
water intrusion, sink  
hole formation





Restored cracks





Restored cracks





Restored cracks





## Knoxville Civic Auditorium and Coliseum Assessment

APPENDIX A2 EAST FACE  
Sheet 16 of 19





Spall coating








Cracked curb






# Knoxville Civic Auditorium and Coliseum Assessment

EAST FACE



NORTH FACE

SOUTH FACE




WEST FACE



# Knoxville Civic Auditorium and Coliseum Assessment

APPENDIX A3 WEST FACE  
Sheet 2 of 27



Knoxville Civic Auditorium and Coliseum Assessment



Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A3 WEST FACE**  
**Sheet 4 of 27**



Tilt up Panels





West Entrance



## Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A3 WEST FACE**  
Sheet 6 of 27



Looking South



## Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A3 WEST FACE**  
**Sheet 7 of 27**






Looking North



























Separation and crack

Crack









## Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A3 WEST FACE**  
**Sheet 20 of 27**







Exposed and rusted rebar

Spalling and exposed rebar

Crack







Separation and settlement

Exposed and rusted rebar


Fragmented concrete  
Spalling and exposed rebar












# Knoxville Civic Auditorium and Coliseum Assessment

EAST FACE



NORTH FACE

SOUTH FACE




WEST FACE



# Knoxville Civic Auditorium and Coliseum Assessment

APPENDIX A4 SOUTH FACE  
Sheet 1 of 31



# Knoxville Civic Auditorium and Coliseum Assessment



Coliseum Service Ramp

HVAC unit Area





Knoxville Civic Auditorium and Coliseum Assessment

**APPENDIX A4 SOUTH FACE**  
Sheet 4 of 15














Dent and separation






Exposed Rebar and Spalling


Water infiltration rust





Spalling





Cracks









Separation at Lintel







Excessive gap

